Idaho PUC Pipeline Safety Inspection Summary

Inspector(s):	spector(s): Perkins/Ulmer			24-25 Sep 19
				T
Company/Owner:	Intermo	untain Gas Company	Unit/OPID:	8160
Inspection Type & Time (1	day)	Tota	l Inspection Days:	3
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	7,			
Standard: Construction: 3 Training: (T)(D) Integrity Management: Incident:				
M/M: Follow-up: OQ: Damage Prevention: D&A:				
Inspection Summary				
A construction inspection was performed on Das-co, a contractor for Intermountain Gas Company.				
24 25 Comt 2010: /2 5 Comptu	atio.ml			
24-25 Sept 2019: (2.5 Construction)				
Observed Dasco crews excavating/potholing and exposing the stub and riser locations at approximately				
15 existing services for riser replacement when the new 2" PE main is installed. Observed the crews				
digging down to locate existing 2" Aldyl-A and digging holes big enough to do the split pull technique				
with new PE. Crews used locating equipment numerous times to locate existing tie-ins. Crew				
additionally dug down and located the 4" steel main in the street where the new 2" PE will tie-in				
Areas observed during this project were: Excavating, line locating, potholing and trenching				
<u>25 Sep 2019:</u> (.5 post Construction)				
Type construction report.				
Attachments:				
IPUC Form 4 Construction Inspections				
Das-co Daily Itineraries located in file for the project.				
OQ's for all observed employees are located in file for the project.				
Corrective Action Required:	I E O II	ow-up Required:	Yes No	X
Yes No		ow-up nequired.	by (date):	<u> </u>
Inspector (Lead):	1001		Date:	
Bruce Perkins	Sher E four	/_	25 Sef 19	9
Reviewer:	1000	1	Date:	
	12/1/1/19	A		2010